

CERTIFIED LAND CORNER RESTORATION

Index No. A-14

State of Wisconsin }
County of Lanlade } ss.

History of original corner establishment:

Corner established in 1930's Resurvey

I Raymond Hallix, do hereby certify that on the 3rd day of July, 1987, I found evidence of the W 1/6 CORNER ~~corner~~ of Section 34 & 3 Township 33 & 32, North, Range 12 E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Description of corner evidence found:

Squared wood post scribed 1/16 S 34, S 3 standing in Rock mound.



Resident witnesses:

.....
.....
.....

Description of monument and accessories I established to perpetuate the original location of this corner.

Set 3" Aluminum pipe with CAP - Rock mound

New BTS
Hard maple 6" S 10° E 36' 9"
" " 12" S 36° W 25' 3"
" " 7" N 31° W 18' 1"
BASSWOOD 10" N 42° E 29' 8"



○ = Corner monument restored.

Dated at Antigo, Wis., this 3rd day of July, 1987

Signature Raymond Hallix Title Land Surveyor Registration No. 5-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

.....
(Register of Deeds)

By..... Deputy