

CERTIFIED LAND CORNER RESTORATION

Index No. A-19

State of Wisconsin }
County of LANGLADE } ss.


History of original corner establishment:

1930 RESURVEY

I RAYMOND S. HALLISY, do hereby certify that on the 30TH day of MARCH, 1985, I found evidence of the Y4 corner of SECTION 35 & 2 Township 32 & 33, North, Range 12, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Description of corner evidence found:

4" IRON PIPE WITH BASS CAP




Resident witnesses:

Description of monument and accessories I established to perpetuate the original location of this corner.

NEW BT'S

9" HARD MAPLE S78W 3.8'
8" BASS WOOD S8W 11.1'
10" HARD MAPLE S56E 15.8'
8" BASS WOOD N1E 18.2'



○ = Corner monument restored.

Dated at ANTIGO, Wis., this 30TH day of MARCH, 1985

Signature Raymond S. Hallisy Title LAND SURVEYOR Registration No. 5685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy