| O = Corr | ner monument | restored. |
|----------|--------------|-----------|
|----------|--------------|-----------|


CERTIFIED LAND CORNER RESTORATION

Index No. B - 20

History of original corner establishment:

Description of corner evidence found:

CORNER ESTABLISHED FROM SUBDIVISION OF SECTION



Description of monument and accessories I established to perpetuate the original location of this corner.

| | ALL E | | 7 "BASSWOOD S 88° W | ζ. Β# | 12"ASPE | THE YILL COR NE 4 SEC 2 T33N • R 13E 5-16-79 W. F. K. |
|---|-------------------------|---------------|------------------------|----------------|---------------|---|
| Dated at | ELCHO | , Wis., this | 16 | day of | YAM | , 19 79 |
| Signature WU | County Surveyor, Regis | U, Title Co | UNTY S | URVEYOR | Regist | |
| Office of Register of instrument was file ato'clock | ed in this office for t | fecord on the | | day of | , I hereby co | ertify that the withi |
| | (Register of De | eds) | | . . | | |