State of Wisconsin

County of LANGLADE

SS.

T 33N - R 13E			
l	1	l	
	 	1	
		· - 	
1	i I	l .	
1	4	1	
1	 	 	
! !	1 1	I I	
	 	l !	

O = Corner monument restored.


CERTIFIED LAND CORNER RESTORATION

Index No. B - /8

History of original corner establishment:

Description of corner evidence found:

CORNER ESTABLISHED FROM



Description of monument and accessories I established to perpetuate the original location of this corner.

13"TAMARACK NW 1/4 SEC.2 T33N + RI3E 5-18-79 W. F. K. BRASS CAP 13"TAMARACK NY74° NY74	PK NAIL IN CROSS
Dated at ELCHO, Wis., this day of MAY, 1 Signature Williams. Kelly Title COUNTY SURVEYOR Registration No. 5 (County Surveyor, Registered Land Surveyor, or other duly authorized official)	
Office of Register of Deeds, County of	9