

CERTIFIED LAND CORNER RESTORATION

33-13 Index No. **J-101**


State of Wisconsin }
County of LANGLADE, } ss.

I, ROBERT J. POSS, do hereby certify that on the 12TH day of AUGUST, 1971, I found evidence of the SECTION corner of SECS. 12, 13, 18, 7 Township 33, North, Range R. 13 EAST & 14 EAST Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

WM WOLF (IN CHR.)


History of original corner establishment:



Description of corner evidence found: FOUND TREES BLAZED & SCRIBED - PROBABLY BY DAVE EDICK BECAUSE OF BEAVER PELT BLAZES. FOUND 2 IRON PIPES 160 FT. APART (SEE SKETCH) ONE HAS SQUARED STAKE BESIDE. (RECENT - 10 YRS. OR SO).

Description of monument and accessories I established to perpetuate the original location of this corner.

- SET 2" IRON PIPE W/ BRASS CAP MKD. R13 R14
- S12 S7
- S13 S18
- 1: CHERRY 4 N 3 1/2 W - BLAZED & SCRIBED.
- 2: CHERRY 6 S 86 W 45.8 (29.8 TO 1 1/2" PIPE) W/ BEAVER PELT BLAZE T 33N RJP.
- 3: POPPLE 10 - 28.3 BEAVER PELT BLAZE & SCRIBE
- 4: CHERRY 4 S 10 W 18.6 BLAZED & SCRIBED.
- BLAZES & SCRIBE MARKS ARE ORIGINAL.
- 0. 2" IRON PIPE - SET W/ BRASS CAP
- 0. 1 1/2" I. PIPE EXISTING
- 0. SQ'D STAKE - SCRIBED



○ = Corner monument restored.

Dated at ELCHO, Wis., this 12TH day of AUGUST, 1971

Signature Robert J. Poss Title REG. LAND SURVEYOR Registration No. S-0001
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy