
## U. S. PUBLIC LAND SURVEY MONUMENT RECORD

INSTRUCTIONS:

This record shall show the location of the corner and shall include all of the following nine elements (a through i).

- (a) Identify the corner by reference to the U.S. public land survey system.
  - = Corner monument restored.

DRIGINAL CORNER ESTABLISHED By JAMES L. NOWLIN IN 1865




(b) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

RESET CORNER MONUMENT FROM TIE-IN TO OWENS-ILLINOIS SURVEY OF SECTION 16, T33N, RISE, DONE IN 1987.

- (c) In the plan view drawing below, provide reference ties to at least 4 witness monuments, or, if the location is within a municipality, to at least 2 witness monuments. (Witness monuments shall be made of concrete, natural stone, iron or other equally durable material.)

  Describe witness monuments.
- (d) Show a plan view drawing depicting the relevant monuments and reference ties which is sufficient in detail to enable accurate relocation of the corner monument if the corner monument is disturbed. Indicate north.



ALL BT's :

- NAIL & RIBBON

N-9

N

Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that
corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing
under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as
restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

NONE.

(f) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location.?

(1)

(g & h) Was the corner reestablished through lost corner proportionate methods? ( show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location.

g) No.

SECTION 15 SE COR., EXISTING COENERS EXISTING SECT. CORNER SECT. 16 REESTABLISHED FROM OWENS-ILLINOIS SURVEY OF SECT. 16

I, WILLIAM F. KELLY

(type or print name)

certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

KELLY S1098 ELCHO.

William J. Jelle Signature

State of Wisconsin

I. WILLIAM F. KELLY, do hereby certify that on the day of OCTOBER, 19.82, I found evidence of the NE corner of SECT. 20

Township 3.3, North, Range

as described hereon; and that from this evidence

I established a new monument and accessories

as described hereon to perpetuate the original

County of LANGLADE

location of this corner.

Resident witnesses:

SS.

## CERTIFIED LAND CORNER RESTORATION


Index No. N-9

History of original corner establishment:

DRIGINAL CORNER ESTABLISHED By JAMES L. NOWLIN IN MAY, 1865.

Description of corner evidence found:

FOUND ROTTED POST & LARGE
STONE WITH "X" ON IT.
REPLACED WITH 3"x 42" AWMINUM
CAP MONUMENT. SCRIBED 3
NEW BT'S.



Description of monument and accessories I established to perpetuate the original location of this corner.

Λ	ALL BT'S NEW	/6" MAPLE	Wer and Convin
North	PK NAIL SET IN "X"	18" MARLE 28.25. SBO'E  SET STONE  PICE AROUND  MONUMENT	DECT. COR.  17 16 20 21  10 - 7 - 82
Dated at	ELCHO	, Wis., this7# day of	OCTOBER , 19 82
Signature		Title COUNTY SURVEYOR Land Surveyor, or other duly authorized official)	Registration No. 1098
instrument	gister of Deeds, County of was filed in this office for reco o'clock	ord on theday of	I hereby certify that the within, 19
	(Register of Deeds	)	
By		Deputy	