CERTIFIED		CORNER	RESTORATION	V
CERTIFIED	LAND	CORNER	RESTURATION	V

Index No. N-7

History of original corner establishment:

ORIGINAL CORNER ESTABLISHED BY JAMES L NOWLIN IN MAY, 1865.

Description of corner evidence found:

FOUND 4x4 SCRIBED POST. SET 3"x 42" ALUMINUM CAP MONUMENT.

FOUND 3 EXISTING BT'S - 1 DEAD.

RESCRIBED OLD BT'S & /NEW BT.

* REPLACED 144 IRON PIPE WITH ALUM. MON.

(Register of Deeds)



William or Kelly

Description of monument and accessories I established to perpetuate the original location of this corner.

βτ's /	OLD DEAD BY OLD DEAD BY IZ! MAPLE OLD DEAD BY VELLOW BIR.	T33N - R 13E
PK NAIL SET	ALL SCRUBED STORMS CAP OLD BT 16" MAPLE) SECT. 25
Dated at ELCHO	, Wis., this	DCTOBER , 1982.
Signature W. Weam 7. Relly (County Surveyor, Regis	Title COUNTY SURVEYOR	Registration No. 1098
•	fday of	· · · · · · · · · · · · · · · · · · ·

•••••••••••••••••••••••••••••••••••••••					
		•••••			
		·			
<u> </u>	733 <i>N</i>	R13E			
	1		1		
	1 1	! !	· ·		
	i I	i I	† 		
	ι ι 5εςτ	i 50 - ' I	[]		
	<u></u> _	; · !	† !		
	 	 	!		
	 	·			
	l 	! !	1		
O = Corner monument restored.					

State of Wisconsin

I WILLIAM F. KELLY, do hereby certify that on the 20th day of October, 1982, I found corner of Sect. 20

as described hereon; and that from this evidence

I established a new monument and accessories

as described hereon to perpetuate the original

County of LANGLADE

location of this corner.

Resident witnesses: