

CERTIFIED LAND CORNER RESTORATION

Index No. R-3

33-13

State of Wisconsin }  
County of Langlade } ss.

I Raymond J. Hallisy, do hereby certify that on the 21st day of April, 1979, I found evidence of the South 1/4 corner of 19 Township 33, North, Range 13 EAST, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

History of original corner establishment:

CORNER SET BY M. HUTCHINSON IN 1928  
COUNTY SURVEYOR

Description of corner evidence found:


1 1/2 inch Iron pipe MANY BLAZES FACING CORNER

Resident witnesses:


.....  
.....  
.....

Description of monument and accessories I established to perpetuate the original location of this corner.

SET 2 inch IRON PIPE WITH BRASS CAP  
NEW B.T.S  
HARD MAPLE 10" 90°W 13' 9"  
" " 7" S39E 11' 10"  
" " 8" N62E 21' 10"



FORM 985 M. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

Dated at ANTIGO, Wis., this 21st day of APRIL, 1979.

Signature Raymond J. Hallisy Title Reg Land Surveyor Registration No. 5685  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of ....., I hereby certify that the within instrument was filed in this office for record on the ..... day of ....., 19..... at ..... o'clock ..... M.

.....  
(Register of Deeds)

By..... Deputy