County of	LANGLAD	E	ss.		
certify that of	on the	, 19 8 RTH	orth, Range Il Meridian accessories		
Resident witnesses:					
UWENS TLLINOIS FORESTR					
DEPT					
T33N, R13E					
		1			
	1 1				
	1	1 1			
	! ! _ _	l			
	1 2				
	1				
	1	<u> </u>			
	1				
	l 				
O = Corner monument restored.					

State of Wisconsin

CERTIFIED LAND CORNER RESTORATION


Index No. R - 19

History of original corner establishment:

ORIGINAL CORNER ESTABLISHED By James Nowlin In 1865

Description of corner evidence found:

FOUND 2" × 2" WOODEN POST WITH LOCATION TAG-REPLACED WITH 2" × 42" BRASS CAP MONUMENT



Description of monument and accessories I established to perpetuate the original location of this corner.

NEW BT's	B" S PRUCE NEW BT	10" SPRUCE EXISTING BT	N 1/4 COR SECT 26
PK NAIL	3. 10 14. 14. 14. 14. 14. 14. 14. 14. 14. 14.	D 2" BRASS CAP MONUMENT "SPRUCE EW BT	T33N + R13E 2.3.81 W-F-K
Dated at ELCHO	, Wis., this 3 rd	day of Fel	o, 19. & İ
Signature William on Ko	Lly Title COUNTY stered Land Surveyor, or other	SURUEYOR duly authorized official)	Registration No. 1098
Office of Register of Deeds, County of instrument was filed in this office for at	record on the	day of	I hereby certify that the within, 19,
(Register of D	ceds)	<u>.</u>	