

CERTIFIED LAND CORNER RESTORATION

23-13

Index No. T-11

State of Wisconsin }
County of LANGLEADE } ss.

I ROBERT J. PAS, do hereby
certify that on the 8TH day
of MAY, 1971, I found
evidence of the CTR. SEC. 28
corner of Sec. 28
Township 33, North, Range
13E, Fourth, Principal Meridian,
as described hereon; and that from this evidence
I established a new monument and accessories
as described hereon to perpetuate the original
location of this corner.

Resident witnesses:

WM. WOLF (Tn. CHRM.)



History of original corner establishment:

Description of corner evidence found:

FOUND IRON PIPE SET BY M. HUTCHINSON CIRCA 1930.
W/ OLD STAKE ALONG SIDE -

Description of monument and accessories I established to perpetuate the original location of this corner.

SET 1/4" PIPE W/ BRASS CAP MD. CTR. SEC. 28.



- 1= HEMK 6 N41E 10.0'
 - 2= CEDAR 8 N51E 42.5' W/OLD CEDAR ALONG SIDE
 - 3= HEMK 3 S32W 10.6' W/BLAZE ON STUMP
- ONLY GOOD TRGES NEAR.

ALL TREES BLAZED & SCRIBED NBT.

Dated at ELCHO, Wis., this 7TH day of JUNE, 1971.

Signature: *Robert J. Pas* Title: REG. LAND SURVEYOR Registration No. S-9901
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within
instrument was filed in this office for record on the _____ day of _____, 19____
at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy

○ = Corner monument restored.

FORM 985 H. C. MILLER CO., MILWAUKEE