CERTIFIED	LAND	CORNER	RESTOR	ATION

			•	-	
				$\boldsymbol{\tau}$	-13
				•	/-
			~		
			_	_	_

History of original corner establishment:

Owens- Illinois survey

Description of corner evidence found:

Found squared stake 3/4th iron pipe and old BTEs

12th Red maple S46E 10'8th 10th Red maple S46W 2'3th

Description of monument and accessories I established to perpetuate the original location of this corner.

Set 2" pipe with brass cap, rock mound


BT's to corner

Yellow Birch

Red Maple N78W 10 Feet 4 inches BT's faced at base of tree and acribed BT

ated at	Antigo	, Wis., this	2th	dav of	June			71
ignature	County Surveyor, Regist	Title Reg.	Land	Surveyor	R	egistratio	n No	1-68
Office of Re	County Surveyor, Register of Deeds County of	ered Land Surveyor, or	other duly	authorized officia	al)	og loti atio		
strument	gister of Deeds, County of was filed in this office for re	ecord on the		day of	, I nerec	y certily	that the	within 9
t(o'clock M.							
	(Register of Dee	ds)						

.Deputy



State of Wisconsin

I Raymond J. Hallisy do hereby

certify that on the 12th day of June , 19 71, I found evidence of the W 1/16

Township. 33 , North, Range

as described hereon; and that from this evidence

I established a new monument and accessories as described hereon to perpetuate the original

13E , Fourth, Principal Meridian,

County of Langlade

corner of 29 & 32

location of this corner.

Resident witnesses:

SS.

O = Corner monument restored.