

CERTIFIED LAND CORNER RESTORATION

33-13

Index No. X-6

State of Wisconsin }  
County of LANGLADE } ss.

History of original corner establishment:

OWENS - ILLINOIS SURVEY

I RAYMOND J. HALLISY do hereby certify that on the 3rd day of JULY 19 71, I found evidence of the West Center 1/16 corner of SECTION 32 Township 33, North, Range 13 EAST, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Description of corner evidence found:

1 1/4 INCH PIPE 4' LONG  
LOCATION POSTER ON 8" MAPLE NORTH 69 W 14 LKS

Resident witnesses:



Description of monument and accessories I established to perpetuate the original location of this corner.

SET 2" PIPE WITH BRASS CAP, ROCK MOUND

BT's TO CORNER

HARD MAPLE 9" S39E 40.9 LKS  
" " 8" N69W 14 LKS

BT's FACED AT BASE OF TREE  
AND SCRIBED BT



○ = Corner monument restored.

Dated at Antigo, Wis., this 3rd day of JULY, 19 71

Signature R. J. Hallisy Title Reg. LAND SURVEYOR Registration No. 685  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of \_\_\_\_\_, I hereby certify that the within instrument was filed in this office for record on the \_\_\_\_\_ day of \_\_\_\_\_, 19 \_\_\_\_\_ at \_\_\_\_\_ o'clock \_\_\_\_\_ M.

(Register of Deeds)

By \_\_\_\_\_ Deputy

FORM 985 H. C. MILLER CO., MILWAUKEE