CERTIFIED	LAND	CODNED	DESTOR	ATION
CERTIFIED	LAND	CURNER	RESTUR	ATION

Index No. X - 11

History of original corner establishment:

Old notes

SŞ.

Description of corner evidence found:

Found 1" square steel rod, pile of rocks

(Register of Deeds)



Long L. Rottes

Description of monument and accessories I established to perpetuate the original location of this corner.



Brąss, Cap	77' \$10°E \$20.5'	W.	Birch
	* 5" W. Bire	ch	
v of December	m	10	78

			* 5" W. Birch
Dated at, Wis	s., this20	day ofDecember	, 1978.
Signature Surveyor, Registered Part	Title Registered	Land Surveyor	Registration No. S-1248
(County Surveyor, Registered Lan	d Surveyor, or other duly	authorized official)	
Office of Register of Deeds, County of		, I h	ereby certify that the within
instrument was filed in this office for record or	n the	day of	, 19
ato'clock			

$\bigcirc = 0$	Corner	monument	restored.
----------------	--------	----------	-----------

State of Wisconsin

County of Langlade

certify that on the 20th day of December , 19 78, I found

evidence of the Center of Section

corner of Section 33

I established a new monument and accessories

as described hereon to perpetuate the original

Sec. 33

Gary A. Radtke

location of this corner.

T.33N.-R.13E.

Resident witnesses: