U.S. PUBLIC LAND SURVEY MONUMENT RECORD

Note: I his form is intended and designed to fulfill all requirements of Wisconsin Administrative Code,	Chapter A	┧-Ŀ 5.02, l	J.S
Public Land Survey Monument Record (3) (a) (b) (c) (d) (e) (f) (g) (h) (i). An additional sheet may	be added i	f necessar	ry to
conform with said requirements.			1
(a) Corner location: Township 33 North			
Range /3 East/West	 		
Town/City/Village Langlade		1	
•	1		1

(b) (f) (g) (h) Description of monument found at this corner and if it was accepted, state all evidence (material, testimonial, occupational, plats, records, other monuments) used as a basis for accepting. If not accepted or if nothing was found, state evidence used as basis for establishing location. If reestablished through lost corner proportionate methods, indicate all monuments, distances and directions used to establish.


Corner not established in original survey.

Langlade

Seymour, 1987, set cor. half-way on line between N 1/4 and C1/4.

(c) (d) (e) Plan view of corner with ties to at least 4 witness monuments. If in disagreement with previously established corner, show the distances between the two corners and also indicate the ties to the disputed corner.

distance to face



+" sugar maple

(i) I Marvin E. Seymour

(type or print name) certify that the corner location on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Marin E. Seymour Signature

July 10, 1987 Date



3