State of Wisconsin

## CERTIFIED LAND CORNER RESTORATION

202745

Wolf Page 10


History of original corner establishment:

Subdivision of township surveyed in 1865 by James L. Mowlin South corrected between section 2 & 3, 42.50 chains

Set wood post

Sugar 10", N 28 E, 8 1ks.

Sugar 7 ", N 19 W, 12 1ks.



1. 5x5 squared cedar post 2 ft. long, scribed

2. Post was found in mound of rock with bottom rotted off, point of post found below rocks.

3. Sugar 19", N28E, 5.28 ft. (81ks.). Tree has many blazes and is hollow.

4. Sugar stump 14", N19W, 7.9 ft. (12 lks.).

Description of monument and accessories I established to perpetuate the original location of this corner.

Replaced point of cedar post with galvanized Iron pipe 5 feet long, 2 ins. inside diameter, filled with concrete and flanged at bottom with brass cap marked

from which the following new bearing trees bear:



y. birch 7", NO50 30' W, 28 lks. elm 4", N 76° 30' E, 15 lks. elm 8", S 28° E, 74 1ks. sugar 10", S78W, 39 1ks.

Drain to Glade Lake 50.0 ft.North Area cover with many rock with high ground to south.

Dated at Rhinelander Signature Vith H. Hedren	Wis., this	day of April	19 63
Jean F. Risvin	Cadastral	Surveyor - U. S.	Government
Signature Victor H. Hedren	Title Cadastral	Surveyor	Registration No.S-185*
(County Surveyor, Registered	Land Surveyor, or other dul	v authorized official) 🥴 D.	arriantal & Appropriad
Office of Register of Deeds, County of	Loughady	, I h	ereby certify that the within.
Office of Register of Deeds, County of instrument was filed in this office for record at	d on the	day of Lide	i, 19.64
at 12 0 Glock M. M. all Millian	je Je		
(Register of Deeds)			
D.,	Danista		いて