## CERTIFIED LAND CORNER RESTORATION

State of Wisconsin	
County of <u>Langlade</u>	S.
I found evidence of the S Township 33 North	, do hereby certify that on the 8th day of October , 19 75 outheast corner of Section 13, Range 14 East , Fourth Principal Meridian, as described nce I established a new monument and accessories as described hereon to per is corner:
Surveyed in 1857 by Artema	Sections 19 and 24 set wood post  ars East 8 Lks. runs S.E.
Description of corner evidence for	und:
Found post point fallen Hemlock S72E, 7 Lks Swamp edge North 11.50 cha 13.90 chains South stream 12.29 Black Ash stump North	ins 8 Lks., runs S.E.
Replaced post point with 2 filled with concrete with 1975, S-802, from which the Maple 8", N77E, 29.29 ft. Maple 8", S44E, 37.85 ft. Maple 7", S61W, 13.36 ft. Maple 10", N57W, 38.91 ft. Chiseled 3 inch square on	SE corner of large rock outcrop which bears N16W, 121.55 ft.
	Resident witnesses
Sec. 13	Dated at Rhinelander Wisconsin, this May of May 19. 76.  Signature Jean F. Resvick Title Land Surveyor (County Surveyor, Registered Land Surveyor, or other duly authorized official)
	Surveyors Registration No. <u>S-802</u>
	Office ofCounty of  I hereby certify that the within instrument was filed in this office for record on theday of
S = Corner monument restored  □ =	on theday ofof County Records.
<u> </u>	SignatureTitle
Townshin 33N Rang	te 14E Section 13 Index No. N-25) Page No.