CERTIFIED LAND CORNER RESTORATION

3	in the Entre Contract Neo	10/1/10/1	
State of Wisconsin			
County of Langlade	S.		
I found evidence of the Southw Township 33 North	est Section cortify that on the core Range 14 East monument a corner:	rner of Section 21	as described
Surveyed in 1865 by J.L. N North between Sections 28 Sections 20, 21, 28 and 29 Birch, 20", N30°E, 35 lks. Hemlock, 30", N32°W, 8 lks Hemlock, 15" Fir, 8" 3 chains South enter swamp 2.5 chains West enter swamp	and 29. 80.0 chains set post NE & SW p SW & NE		
Description of corner evidence for	und:		
Hemlock stump hole, N32°W, No evidence of the birch w 2.5 chains West enter swam 4.0 chains South enter swa In 1937 Nels Sandberg repo	as found P	Birch bearing trees	
Description of monument and acc	cessories I established to perpetuate	the location of this corner:	
I replaced the post with a	2 inch inside diameter galva oncrete, with a brass cap sta S29, 1978, S-1107 ear:	anized iron pipe,	
		wisconsin . O	
		SURV. SURV. SEE BEEFE	
	Resident witnesses	7,0,000	······
	Dated atLaona	Wisconsin, this 25 day of	July
	40. 70		•
Sec. 21	Signature. William B. Cochrane		
	Surveyors Registration No. S-1107		
	Office of	County of	
	Office of! hereby certify that the within in	_	
Corner monument restored	on theday of	19, and was f	
- _	NoPage No	of County Records.	
	Signature	Title	