

CERTIFIED LAND CORNER RESTORATION

State of Wisconsin }  
County of Langlade } ss.

I, Milo E. Stefan, do hereby certify that on the 14th day of October 1982, I found evidence of the West Quarter corner of Section 21 Township 33 North, Range 14 East, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner:

Description of original monument and accessories and subsequent restorations:


Surveyed in 1865 by J. L. Nowlin  
40.00 chains, set wood post  
Cedar, 15", S47°E, 3 lks.  
Hemlock, 12", N20°W, 15 lks.

Description of corner evidence found:

Found a 4" x 4" x 30" scribed Cedar post--very likely original  
Stump hole the size of a large Cedar, S47°E, 3 lks.

Description of monument and accessories I established to perpetuate the location of this corner:

Placed a 2" x 60" aluminum monument with tablet stamped as follows:  
T33N, R14E, 1/4, S20, S21, 1982, RLS-1558  
From which the following bear:  
White Spruce, 5", N69°E, 15.60'  
White Birch, 6", S18°E, 21.82'  
White Spruce, 6", S68°W, 19.52'  
Black Spruce, 4", N4°W, 14.52'  
Steel Sign Post, South, 1.8'



● - Corner monument restored  
□ -

Resident witnesses.....

Dated at Rhinelander, Wisconsin, this 14th day of October 1982.

Signature Milo E. Stefan Title Land Surveyor  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Surveyors Registration No. RLS-1558

Office of COUNTY SURVEYOR County of LANGLADE

I hereby certify that the within instrument was filed in this office for record on the 31st day of JAN 1984, and was filed in Book No. .... Page No. .... of County Records.

Signature William J. Kelly Title County Surveyor

Township 33 North, Range 14 East, Section 21, Index No. P-9, Page No. 46