

CERTIFIED LAND CORNER RESTORATION

State of Wisconsin }
County of Langlade } ss.

I Jean F. Resvick, do hereby certify that on the 6 day of November 1978, I found evidence of the Northeast Section corner of Section 28 Township 33 North Range 14 East Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner:

Description of original monument and accessories and subsequent restorations:

Survey in 1865 by J.L. Nowlin
80 chains North between Sections 27 & 28, set post
Tamarack 8, N69E, 35 lks.
Tamarack 10, N30W, 30 lks.
Tamarack 15
Cedar 8
35 chains South leave swamp, bears SW-NE
10 chains East leave swamp, bears SW-NE
35 chains North leave swamp, bears E-W

Description of corner evidence found:



6x6 scribed cedar post
Tamarack stump, scribed, N69E, 23.10 feet
Tamarack stump, N25W, 19.8 feet
35 chains North leave swamp

Description of monument and accessories I established to perpetuate the location of this corner:

Replaced 6x6 post with a 2 inch inside diameter aluminum pipe, 5 feet long, with driving point, and a cast aluminum cap stamped T33N, R14E, S21, S22, S28, S27, 1978, S-802

Blazed and scribed the following new bearing trees:

Cedar 9, N27E, 29.96 feet
Cedar 11, S41E, 31.10 feet
Cedar 9, S64W, 34.65 feet
Cedar 10, N16W, 17.02 feet



● - Corner monument restored
□ -

Resident witnesses.....

Dated at Rhineland Wisconsin, this 6 day of November 1978..

Signature Jean F. Resvick Title Land Surveyor
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Surveyors Registration No. S-802

Office of..... County of.....

I hereby certify that the within instrument was filed in this office for record on the..... day of..... 19....., and was filed in Book No. Page No. of County Records.

Signature..... Title.....

Township 33 North, Range 14 East, Section 28, Index No. R-13, Page No.

R-13
↑