

CERTIFIED LAND CORNER RESTORATION

State of Wisconsin }
County of Langlade } ss.

I Milo E. Stefan, do hereby certify that on the 26th day of October 1982, I found evidence of the North Quarter corner of Section 28 Township 33N, Range 14E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner:

Description of original monument and accessories and subsequent restorations:


Surveyed in 1865 by J. L. Nowlin
40.21 chains, set wood post
Spruce, 8", S51°E, 8 lks.
Cedar, 10", N12°W, 10 lks.

Description of corner evidence found:

No original evidence found
Local Evidence: Cedar, 6", scribed, S80°E, 17.77'
Cedar, 12", faced out, but scribing appears rotted out, S W
(chopped out and no evidence was found of scribing)

Description of monument and accessories I established to perpetuate the location of this corner:

Placed a 2" x 60" aluminum monument stamped as follows:
T33N, R14E, S21, 1/4, S28, 1982, RLS-1558
From which the following bear:
Cedar, 8", N75°E, 18.00'
Cedar, 10", S80°E, 17.77'
Cedar, 8", S11°W, 6.10'
Cedar, 6", N28°W, 15.78'
Steel Sign Post, SW, 1.8'



● - Corner monument restored
□ -

Resident witnesses.....

Dated at Rhinelander Wisconsin, this 2 day of MAY 1982..

Signature Milo E. Stefan Title Land Surveyor
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Surveyors Registration No. RLS-1558.....

Office of..... County of.....

I hereby certify that the within instrument was filed in this office for record on the..... day of..... 19....., and was filed in Book No..... Page No..... of County Records.

Signature..... Title.....

R-11