


# U. S. PUBLIC LAND SURVEY MONUMENT RECORD.

**INSTRUCTIONS:** This record shall show the location of the corner and shall include all of the following nine elements (a through i).

- (a) Identify the corner by reference to the U.S. public land survey system.  
 O - Corner monument restored.

Section corner common to Sections 4, 5, 32, and 33, T.32-33N., R.14E., Langlade County, Wisconsin.



- (b) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

In 1857, A. Millard set wood post and made the following B.T.'s: Y. Birch, 20", N.50°W., 53 links (34.98 feet); Sugar, 10", N.26°E., 29 links (19.14 feet); Sugar, 14", S.34°E., 28 links (18.48 feet); Y. Birch, 12", S.59°W., 60 links (39.60 feet).

In 1933, R. Kolbe found a 30" hardwood stake.


In 1982, M. Stefan found a post point and location poster. Located stump holes at Northeast, Southeast, and Southwest original B.T. locations. Accepted position as perpetuation of original corner.

In 1989, Alan Harrison found corner and accessories by Stefan.

- (c) In the plan view drawing below, provide reference ties to at least 4 witness monuments, or, if the location is within a municipality, to at least 2 witness monuments. (Witness monuments shall be made of concrete, natural stone, iron or other equally durable material.) Describe witness monuments.

- (d) Show a plan view drawing depicting the relevant monuments and reference ties which is sufficient in detail to enable accurate relocation of the corner monument if the corner monument is disturbed. Indicate north.

1. 2 1/2" x 36" aluminum monument stamped to identify corner location.
2. Basswood, 12", N.25°E., 29.27 feet.
3. Sugar, 6", S.46°E. 35.81 feet.
4. Sugar, 6", S.72°W., 22.38 feet.
5. Sugar, 6", N.63°W., 13.84 feet.
6. Steel sign post, North, 1.85 feet.



(e) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

None.

(f) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

(2) a found perpetuated location.

(g&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?

No.


Checked 12-21-89

*M. S. Kelly*

(i) I, Alan D. Harrison  
[type or print name] certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

*Alan D. Harrison*  
Signature

12/1/89  
Date



CERTIFICATE READY FOR FILING:

*Tommy S. Hruska*  
District Ranger

CERTIFIED LAND CORNER RESTORATION

State of Wisconsin }  
County of Langlade } ss.

I, Milo E. Stefan, do hereby certify that on the 26th day of October, 1982, I found evidence of the Northwest corner of Section 4 Township 33N, Range 14E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner:

Description of original monument and accessories and subsequent restorations:

Surveyed in 1857 by Alfred Millard  
80.00 chains, set wood post  
Sugar, 10", N26°E, 29 lks., 19.14'  
Sugar, 14", S34°E, 28 lks., 18.48'  
Yellow Birch, 12", S59°W, 60 lks., 39.60'  
Yellow Birch, 20", N30°W, 53 lks., 34.98'


Description of corner evidence found:

Stump hole, N26°E, 19'  
Stump hole, S34°E, 18.5'  
Stump hole, S59°W, 40.0'  
Local Evidence: DNR location poster on 6" Sugar Maple, S32°E, 13.2'  
Fallen 8" x 5' Cedar post with location poster (CCC period)

Description of monument and accessories I established to perpetuate the location of this corner:

Placed a 2" x 36" aluminum monument in a mound of stone with tablet stamped as follows:  
T33N, R14E, S32, S33, S5, S4, T32N, 1982, RLS-1558  
From which the following bear:  
Basswood, 12", N25°E, 29.27'  
Sugar, 6", S46°E, 35.81'  
Sugar, 6", S72°W, 22.38'  
Sugar, 6", N63°W, 13.84'  
Steel Sign Post, North, 1.85'

SW COR SECT 33  
T 33 N R 14 E



● - Corner monument restored  
□ -

Resident witnesses.....

Dated at Rhinelander Wisconsin, this 2 day of MAY 1982.

Signature Milo E. Stefan Title Land Surveyor  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Surveyors Registration No. RLS-1558

Office of..... County of.....

I hereby certify that the within instrument was filed in this office for record on the..... day of..... 19....., and was filed in Book No..... Page No..... of County Records.

Signature..... Title.....