


INSTRUCTIONS:

This record shall show the location of the corner and shall include all of the following nine elements (a through I).

Identify the corner by reference to the U.S. reference to the U.S. public land survey system,

O - Corner monument restored.

Quarter corner to sections 4 and 33, T.32-33N., R.14E., Langlade County, Wisconsin.



Describe any record evidence, monument evidence, occupational evidence, teatimonisi evidence or any other material evidence you considered, and whether the monument was found or placed.


In 1857, Alfred Millard set a wood pst with the following B.T.s: Elm, 22", S55°W, 17 links (11.22 feet); Basswood, 10", N65°E, 15 links (9.90 feet).

In 1989, Alan Harrison (RLS) searched and found east/west blazed line but no evidence of corner. Set corner using proportional method.

- in the plan view drawing below, provide reference ties to at least 4 witness monuments, or, the location is within a municipality, to at least 2 witness monuments. (Witness monuments shall be made of concrete, natural stone, iron or other equally durable material.)

 Describe witness monuments.
- Show a plan view drawing depicting the relevant monuments and reference ties which is sufficient in detail to enable accurate relocation of the corner monument if the corner monument is disturbed. (0) Indicate north.
 - $2\frac{1}{2}$ " x 36" aluminum monument with tablet stamped to identify the corner location.

 - Sugar, 11", N12°E, 29.52 feet. Sugar, 12", S76°W, 16.91 feet. Sugar, 11", S28°E, 20.38 feet. 3.
 - 4.
 - 5. Steel sign post, West, 1.21 feet.



Book 10, Page 1

(e) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner os previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

None.

(f) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?


No.

(9&h) was the corner reestablished through lost corner proportionate mathods? If so, show the method, including the directions and distances to other public tend survey corners used as evidence or used for proportioning in determining the corner location?

Yes.

S 89-41-46 E

5280.721



Alan D. Harrison

12-71-69

1 type or print name) cortify that the corner location the

type or print name) certify that the corner location shown un this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record I correct and complete to the best of my knowledge and belief.

rour

11/29/89

CERTIFICATE READY FOR FILING:

District Ranger



ALAN D. THARRISON S-1651

WABENO

O SURV