

CERTIFIED LAND CORNER RESTORATION

State of Wisconsin }
County of LANGLADE } ss.

History of original corner establishment:

CORNER SET IN 1937 BY T. H. KILROE AND D. A. HINTZ
COUNTY RESURVEY PROJECT

I RAYMOND J. HALLISY, do hereby certify that on the 13 day of MAY, 1969, I found evidence of the W 1/16 corner of SEC 1 Township 34N, North, Range 9E, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Description of corner evidence found:


OLD CEDAR POST - TOP BROKE OFF - POINT IN GROUND
LOCATION POSTER ON ROAD - 4 CHAINS EAST
NO B.T.'S

Resident witnesses:

GERALD WEIX
JERRY KEYKA

Description of monument and accessories I established to perpetuate the original location of this corner.

SET 2" IRON PIPE WITH BRASS CAP AND ROCK MOUND
MARKED
T 34N R 9E
SEC 1
SEC 13
W 1/16
BEARING TREES MARKED WITH "B.T."
WHITE BIRCH 10" N29°W 13'5"
WHITE PINE 8" N25°E 34'2"



○ = Corner monument restored.

Dated at ANTIGO, Wis., this 4 day of JUNE, 1969.

Signature Raymond J. Hallisy Title Reg. Land Surveyor Registration No. S-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy

FORM 985 M. C. MILLER CO., MILWAUKEE