	_		
	•	' 	1
	•	, I	
	!	!	<del>   </del>
	! 	' !	, 1
	•		1
1	cal		ı
	_ <u>2@27</u> /	10 <u>10</u> 10	¦
ĺ	134N	RGE	1
1		l	ı
!		ļ .	1
		¦	<del> -                                    </del>
ı	1		l
·	1		1
1	į		

O = Corner monument restored.

## CERTIFIED LAND CORNER RESTORATION

Index No. 6-14

History of original corner establishment:

Corner set in the 1930 resurvey.

Description of corner evidence found:

Squared wood post down, point in ground

Description of monument and accessories I established to perpetuate the original location of this corner.

Reset wood post and surrounded it with a rock mound.

New BT's

811	Yellow Birch	n38w	31.4 Links
711	Black Ash	<b>S</b> 54E	25.5 "
Oti	Pod Manle	chr	22 1. 11

Ω	Antig	70	Wis., this	2nd		day of	May	1981
Mine	nd	Halle	<b>U</b> Title	Req.	Land	Surveyor		Registration No. S-685
(Cou	nty Sar	eyor, Registered	Land Surve	yor, or o	ther duly	authorized of	ficial)	
gister of I	Deeds	County of	<u> </u>			•••••	<b>,</b> ]	I hereby certify that the within
was filed i	in this	office for recor	d on the			day o	f	, 19
'clock		M.						
	(Re	gister of Deeds)		•••••				
	was filed	was filed in this o	Antigo  (County Sarveyor, Registered gister of Deeds County of	was filed in this office for record on the Clock	was filed in this office for record on the	was filed in this office for record on the	was filed in this office for record on theday o	