

CERTIFIED LAND CORNER RESTORATION

State of Wisconsin }
County of Langlade } ss.

History of original corner establishment:

I Raymond J. Hallisy, do hereby certify that on the 5th day of July, 1969, I found evidence of the M.C. corner of Section 7 Township T34, North, Range 9E, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Corner set in 1961 by Keith Hall for the Perch Lake Plat.

Description of corner evidence found:

Found 1 1/2" iron pipe with a wood picket underground.
R.T.'s
18" White Pine NSW 17ft. 8 inches
18" Red Pine N54E 13ft. 3 inches


Resident witnesses:

R.T.'s in good shape

Description of monument and accessories I established to perpetuate the original location of this corner.

Set 4" brass cap in cement
No new R.T.'s

FORM 985 M. C. MILLER CO., MILWAUKEE



Dated at Antigo, Wis., this 5th day of July, 1969.

Signature Raymond J. Hallisy Title Reg. Land Surveyor Registration No. S-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy

○ = Corner monument restored.