

CERTIFIED LAND CORNER RESTORATION

Index No. **G-9**

State of Wisconsin }
County of LANGHAOLE } ss.


History of original corner establishment:

1930's COUNTY RESURVEY PROJECT

I RAYMOND J. HANNISY, do hereby certify that on the 9 day of MAY, 1981, I found evidence of the WEST ONE QUARTER (1/4) corner of SEC. 9 Township 34, North, Range 9E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Description of corner evidence found: **4" BRASS CAP**

26" WH. PINE STUMP - ROTTEN
NB90W 62 LINKS
SCRIBES NOT VISIBLE



Resident witnesses:


Description of monument and accessories I established to perpetuate the original location of this corner.

BRASS CAP IN PLACE

NEW BEARING TREES

- 9" BLACK CHERRY N46°E 10.00 FEET (OLD BLAZE)**
- 12" RED MAPLE N86°E 13.80 FEET**
- 7" HARD MAPLE S70°E 17.40 FEET**
- 8" HARD MAPLE N80°W 27.10 FEET**

FORM 985 H. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

Dated at ANTIGO, Wis., this 9 day of MAY, 1981

Signature Raymond J. Hannisy Title REG. LAND SURVEYOR Registration No. 5-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19..... at..... o'clock..... M.

.....
(Register of Deeds)

By..... Deputy