

CERTIFIED LAND CORNER RESTORATION


Index No. F-9

State of Wisconsin }
County of LAWGLADE } ss.

I RAYMOND J. HALLSY, do hereby certify that on the 9 day of MAY, 1981, I found evidence of the N 1/16 corner of SECTION 9 Township 34, North, Range 9E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

.....
.....
.....



○ = Corner monument restored.

History of original corner establishment:

1930's COUNTY RESURVEY PROJECT

Description of corner evidence found:


4 INCH SQUARE POST

Description of monument and accessories I established to perpetuate the original location of this corner.

2" BRASS CAP

9" WHITE PINE S27°W 35.00 FEET

7" YELLOW BIRCH S40°E 23.30 FEET



Dated at ANTIGO, Wis., this 9 day of MAY, 1981.

Signature Raymond J. Hallsy Title REG. LAND SURVEYOR Registration No. 5-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19..... at..... o'clock..... M.

.....
(Register of Deeds)

By..... Deputy