

CERTIFIED LAND CORNER RESTORATION

State of Wisconsin }
County of Laneshade } ss.

History of original corner establishment:

Corner set in the 1930 resurvey.

I Raymond J. Hallisy do hereby certify that on the 29th day of August, 1970, I found evidence of the E 1/16 corner of Section 15 Township 34, North, Range 9E, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Description of corner evidence found:

Found old stake standing, rock mound. Marked 1/8 S

Resident witnesses:

.....
.....
.....

Description of monument and accessories I established to perpetuate the original location of this corner.


Set 2" pipe with brass cap, rock mound.

New B.T.'S

10" Elm S52E 20 Ft. 9 Inches
10 Hard Maple S12E 15 Ft. 3 Inches



B.T.'s faced at base of tree and scribed BT



Dated at Antigo, Wis., this 29th day of August, 1970.

Signature Raymond J. Hallisy Title Reg. Land Surveyor Registration No. S-685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

.....
(Register of Deeds)

By _____ Deputy

○ = Corner monument restored.

FORM 985 M. C. MILLER CO., MILWAUKEE