State of Wisconsin								
County of LANGLADE ss.								
I								
Resident witnesses:								
John Drew								
Donald Kelly								
T34N-RIOE								


	T 34N- RIOE										
	-	1	I	l							
		l :	 	l I							
			_								
		· · · · · · · · · · · · · · · · · · ·	' 								
4)		7	¦ 							
İ	!	 	i 1	! !							
	_ _ _ _	 	! !	 -							
I		! ! • . !	 								

O = Corner monument restored.

CERTIFIED LAND CORNER RESTORATION

History of original corner establishment:

4" BRASS CAP SET BY T.H. KILROE IN THE 1930'8.



Description of corner evidence found:

CORNER LOCATED ON A RIDGE IN A CELAR & HEMLOCK SWAMP AREA. IDENTIFIED BY RESILENT WITNESSES.

NOTE: THE ORIENTATION OF THE N-S LINE ON THE BRASS CAP IS RUNNING N65°E.

Description of	monument and a	ccessories I esta	iblished to perpeti	ate the ori	iginal location	of this corner		
1.	25. 3. 3. A. P. C. S.	,4" BRASS CAF			BRASS C	AP MARKED:	512 T34N R9E	57 T34N RIOE
(4" HEML OLD BLAZ	SUSTILL STILL STIL	5 70 E	OOLD HOLLOW C STUMP WITH B MARK, BLAZE HARD MAPLE	LAZE	TREES BLA A + AT BA	ZED nbt on Se.	TRUNK W	il-Roe ITH
Dated at	ELCHO	, Wis.,	this 50	day of	APRIL		, 19. 7	5
Signature <i>M</i>	County Surveyor	Registered Land	itle REGISTERED Surveyor, or other de	LAND SUF	RVEYOR	Registration	No. 8 109	B
instrument was	ter of Deeds, Cous filed in this offic	e for record on	the	day	, I he	reby certify tl	hat the wit	hin
	(Registe	r of Deeds)						
Ву			Depu	ty				