

CERTIFIED LAND CORNER RESTORATION

State of Wisconsin }
County of Lan glade } ss.

History of original corner establishment:

Corner set in the 1930 resurvey.

I Raymond J. Hallisy do hereby certify that on the 6th day of June, 19 71, I found evidence of the W 1/16 corner of Section 14 & 23 Township 34, North, Range 9E, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Description of corner evidence found:

Found wood stake standing marking not plain.


Resident witnesses:

.....
.....
.....


Description of monument and accessories I established to perpetuate the original location of this corner.

Set 2" pipe with brass cap, rock mound.

BT's to corner
10" Spruce S18E 12 Feet 8 inches
5" Tamarack S50W 8 Feet 8 inches
BT's scribed at base of tree and faced.



FORM 985 M. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

Dated at Antigo, Wis., this 6th day of June, 19 71

Signature R. J. Hallisy Title Reg. Land Surveyor Registration No. 085
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of....., I hereby certify that the within instrument was filed in this office for record on the.....day of....., 19..... at.....o'clock..... M.

.....
(Register of Deeds)

By.....Deputy