

CERTIFIED LAND CORNER RESTORATION

34-9

Index No. R-24

State of Wisconsin }  
County of Langlade } ss.

History of original corner establishment:

I Raymond J. Hallisy do hereby certify that on the 25th day of July, 19 70, I found evidence of the E 1/16 corner of Section 25 Township 34, North, Range 9E, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Corner set in the 1930 resurvey.

Description of corner evidence found:

Found old location poster marked - corner  $1\frac{1}{2}$  chains north. Post gone, found hole and rock mound. Four blazed trees facing hole. blazed lines North, ~~XXXX~~ South & East.


Resident witnesses:

.....  
.....  
.....


Description of monument and accessories I established to perpetuate the original location of this corner.

Set 2" iron pipe with brass cap, rock mound.

New B.T.'s  
10" Hard Maple S79W 11 Ft. 8 Inches  
10" Hard Maple N75E 16 Ft.  $\frac{1}{2}$  Inch



B.T.'s faced at base of tree and scribed BT.



○ = Corner monument restored.

Dated at Antigo, Wis., this 25th day of July, 19 70

Signature Raymond J. Hallisy Title Reg. Land Surveyor Registration No. S-685  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of \_\_\_\_\_, I hereby certify that the within instrument was filed in this office for record on the \_\_\_\_\_ day of \_\_\_\_\_, 19 \_\_\_\_\_ at \_\_\_\_\_ o'clock \_\_\_\_\_ M.

(Register of Deeds)

By \_\_\_\_\_ Deputy

FORM 985 H. C. MILLER CO., MILWAUKEE