
SS.

State	of	Wisconsin

County of Langlade

I Raymond J. Hallisy do hereby certify that on the 6th day of June , 19.71, I found evidence of the 2 corner of Section 30 & 29 Township 34, North, Range 9E , Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:



O = Corner monument restored.

CERTIFIED LAND CORNER RESTORATION

Index No. 7-3

History of original corner establishment:

Corner set in the 1930 resurvey.

Description of corner evidence found:

Reset corner 80 Feet XX East of true corner, because of road improvement.

Description of monument and accessories I established to perpetuate the original location of this corner.

Set 4" brass cap in cement BT's to witness corner SILE 43 Feet 9 inches 6" Red Maple 40 Feet 2 inches 8" Cedar BT's faced at base of tree and scribed BT.



Dated at Antingo	Wis., this 6th	June	71
Dated at Ant Dgo Signature County Surveyor, Registere	Title Reg. Land	Surveyor	Registration No. 685
Office of Register of Deeds, County of instrument was filed in this office for reco	rd on the	, I he	ereby certify that the within
(Register of Deeds)			
D _v ,	Damusta		

	ب	/	L	/2
Г				ı
1				1
				١
ı				ļ
-	_	_	_	4
ı				

CERTIFIED	LAND	CORNER	RESTORATION
V=::::::=D		001111211	11201011/111011

34-9 Index No. T-5

History of original corner establishment:

1937

Description of corner evidence found:

4" IRON PIPE W. TA BRASS CAP WE 30 FT WEST OF CORNER

Description of monument and accessories I established to perpetuate the original location of this corner.

SET SAME PIPE 80FT EAST OF CORNER

Dated at....., Wis., this.....day of......, 19....... Office of Register of Deeds, County of......, I hereby certify that the within instrument was filed in this office for record on the ______day of _______19_____ at.......o'clock...... M. (Register of Deeds)

O = Corner monument restored.

State of Wisconsin

I G. MEKENNA + C. WEIX, do hereby certify that on the _____day

of August 19.63, I found evidence of the y^{μ} corner of y^{μ}

Township 34, North, Range , North Principal Meridian,

as described hereon; and that from this evidence

I established a new monument and accessories as described hereon to perpetuate the original

County of LANGLADE

location of this corner.

Resident witnesses:

State of Wisconsin	ss.
County of Langlado	} 33.
certify that on the 24 6/2 of Acquisite of the W.C. 70 /4 corner of 5867/00 29, 36. Township 34 , Nourth Princip as described hereon; and that from I established a new monument and as described hereon to perpetuate location of this corner.	North, Range oal Meridian, this evidence d accessories
Resident witnesses:	
i	1
	1
	1
	! !
SECTION 30_	¦ d
	i I
	
	1
	<u>'</u>

O = Corner monument restored.

CERTIFIED LAND CORNER RESTORATION

Index No. T - 5

History of original corner establishment:

1930 RESURVEY

Description of corner evidence found:

* WHITE PINE STUMP BT TO W.C. NI3W 8.6 LKS
4" PIPE W.C. 80 FT EAST OF TRUE CORNER

Description of monument and accessories I established to perpetuate the original location of this corner.

SET 2" IRON PIPE WITH BRASS CAP W.C.

NO NEW BT, 3



Dated at Astigo		th day of	August	, 19.74.
Dated at April 190 Signature (County Surveyor, Register	Title Leg.	Land Survey	M Registr	ation No. 5-685
Office of Register of Deeds, County of instrument was filed in this office for rec			, I hereby cer	tify that the within
at	ord on the	day 01.		**********************************
(Register of Deed	s)			