	K. Pleoge	=	, do nereby	
certify that	on the3	lst	day	
of Dec	ember	, 19.	.80, I found	
evidence of	the Sect	ion	·	
corner of	Sections	5 <b>,</b> 6, 31	., 32	
Township	33 and	34 ,	North, Range	
			ipal Meridian,	
as described	hereon; and	l that from	this evidence	
I established	d a new mo	nument a	nd accessories	
as described	l hereon to	perpetuat	e the original	
location of t	his corner.		188888888888888888888888888888888888888	
		311911	CON	
Resident wi	tnesses:	Su. W.	CONSIDERATEL	1/2
		§ /	DANIFI	1
		<b>3</b> /	K	•
				23
		<u> </u>	\$-1537	~ ~∵
		<b>EP</b> \	WTIGO, WAS	"
		3/	A. J. September 1	3
		3,00	SUDVE N	•
		000	100000000000	
	23321	R9E		)
<u> </u>	T33N	R9E	<del>- 9</del>	)
	23321	R9E	1 S.C.	)
	23321	R9E   	<del>- 9</del>	)
	23321	R9E	<del>- 9</del>	)
	23321	R9E	<del>- 9</del>	)
	23321	R9E	<del>- 9</del>	)
	23321	R9E	<del>- 9</del>	)
	23321		<del>- 9</del>	)
	23321	R9E	<del>- 9</del>	)
	23321		<del>- 9</del>	)
	23321		<del>- 9</del>	)
	23321		<del>- 9</del>	)
	23321		<del>- 9</del>	)
	23321		<del>- 9</del>	)
	23321		<del>- 9</del>	)
	23321		<del>- 9</del>	
	23321		<del>- 9</del>	)
	23321		<del>- 9</del>	

State of Wisconsin

County of Langlade

SS.

CERTIFIED LAND CORNER RESTORATION

Index No. A - 5

S1537 - 1980

History of original corner establishment:

Original corner established by H.C. Fellows, deputy surveyor, in 1859 from which Sugar 20" bears N53 $^{\rm O}$ W 20 links, Spruce 10" bears S30 $^{\rm O}$ W 8 links, Sugar 10" bears S20 $^{\rm O}$ E 20 links, Sugar 10" bears N40 $^{\rm O}$ E 20 links.

Description of corner evidence found:

Recovered a 1" iron rod 2-1/2 feet below road surface of C.T.H. "H" - rod is driven in original road bed. This position falls in line with fence line which runs East and Town Line Road which runs west. Recovered a 4" diameter iron pipe with brass cap N50°W 52.40 feet of iron rod. Brass cap stamped:

As witness corner recovered conflicts with iron rod, I believe that the W.C. has been disturbed and moved by road construction. Witness Corner falls in west ditch line next to a new culvert. I don't believe the culvert could have been replaced without moving the witness corner.

T34N R9E

S31 | S32

S6 | S5

T33N R9E

45 Degrees SE

Description of monument and accessories I established to perpetuate the original location of this corner. 42.4 ft.

Dated at Rhinelander , Wis., this 23rd day of March , 19.81.

Signature David K. Pleage Title Registered Land Surveyor Registration No. 1537 (County Surveyor Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of , I hereby certify that the within instrument was filed in this office for record on the day of , 19.

(Register of Deeds)