


CERTIFIED LAND CORNER RESTORATION



Index No. E-15

State of Wisconsin }
County of LANGLADE } ss.

I WILLIAM F. KELLY, do hereby certify that on the 30TH day of DECEMBER, 1976, I found evidence of the MEANDER corner of SECTIONS 3 & 10 Township 34, North, Range 10E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

.....
.....
.....


History of original corner establishment:

Description of corner evidence found:


4" IRON PIPE WITH BRASS CAP. SET ON 1937 RESURVEY.

William F. Kelly 12-30-76

Description of monument and accessories I established to perpetuate the original location of this corner.
MARKED WITNESS TREES.



FORM 985 H. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

Dated at ELCHO, Wis., this 30TH day of DECEMBER, 1976

Signature William F. Kelly Title REGISTERED LAND SURVEYOR Registration No. 51098
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy