LANGLADE COUNTY U.S. PUBLIC LAND CORNER RESTORATION

The South Quarter corner of Section 9, T. 34 N., R. 10 E., Langlade County, WI.


Corner was: (check all that apply)					
	Restored through acceptance of an obliterated evidence location.				
X	Restored through acceptance of a found perpetuated location.				
	Determined to be lost and re-established through proportionate methods				
_	Show bearings and distances to PLSS corners used for proportioning, and show original dist	ances).			
	Restored/recovered/re-established in a location that differs from a previously established position	,			
	(Show difference in plan view below).				
	Check here if addition information is shown on the reverse side of this form.				
Descr	ribe record evidence, recovered physical evidence, occupational evidence, testimonia	al			
evidence and all other evidence considered in the recovery/restoration of the corner.					

The original corner was established in 1865 by James L. Nowlin. Original bearing trees: tamarac, 4", \$74°W, Il links and a tamarac, 5", \$100°E, 7 links. Brooks, date unknown, marked new BT's tamarac, 8", \$100°C, \$1

Physical description of the monument set:

For the corner, I re-set the 1937 monument, a 4" iron pipe with brass cap, as described above. Set a white vinyl sign post 1' north of the corner monument.


Describe the accessories used to perpetuate the corner. Include a plan view drawing and accessories found/set. Describe measuring point on bearing trees. Show any topographic



State	OI WIS		1
County of	LANGLADE		} SS.
LITTIT	AN E VE	7 T V	
	AM F. AL	8th	, do hereby
certily that	on the APRIL	<u></u> 10	
evidence of	the 1/4 S	ECTION	
orner of S	ECTIONS	9 & 16	
Township	34		, North, Range cipal Meridian
o describe	, t	ourth Prin	cipal Meridian n this evidence
			and accessories
			te the origina
ocation of	this corner	•	
Resident w	itnessos		
Resident w.	Itilesses.		
J. DREW	· · · · · · · · · · · · · · · · · · ·		
			······
	T 341	1 - RIDE	
	_T 34A	- <i>RIDE</i>	
	Т <i>34</i> л	- RIOE	
	T 34A	- RIDE 	
	T 34A	- RIOE	
		- RIDE -	
	T 346	- RIDE	
	T 34A	1-RIDE	
	T 34A	1 - RIDE	
	T 34A	1-RIDE	
	T 34A	1-RIDE	
	T 34A	1 - RIDE	
	T 34A	1-RIOE	
	T 34A	1-RIDE	
	T34A	1-RIDE	

CERTIFIED	LAND	CORNER	RESTORA	TION

History of original corner.establishment:



Description of corner evidence found:

4" BRASS CAP SET IN CONCRETE IN A 4" PIPE.

CORNER IS LOCATED IN A SPRUCE SWAMP APPROXIMATELY 200 FEET NORTH OF BASS LAKE ROAD.

Description of monume	NBT 6" BLACK	S I establishe		ate the origin	BRASS CAP MARK CORNER WITNESS WITH NEW BEARI TREES.	ED: ANT 34N RIC
NET 8" BLACK SPRUCE	Seuth 200'			RING TREES AT BASE.	SCRIBED NBT ON	TRUNK WITH
Dated at ELCHO	TOWN ROAD	., Wis., this	811	day of	APRIL	, 19 75
Signature Willia (Count	y Surveyor, Register	ed Land Survey	or, or other di	ıly authorized o	fficial)	
Office of Register of De instrument was filed in ato'clock	this office for rec	ord on the		day o	, I hereby cert	ify that the within
	(Register of Deeds	s)				