

CERTIFIED LAND CORNER RESTORATION

34-10


Index No. H-17

State of Wisconsin }
County of Langlade } ss.

I, Raymond J. Hallisy, do hereby certify that on the 14th day of May, 19 69, I found evidence of the S 1/16 corner of Section 11 Township 34, North, Range 10E, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

.....
.....
.....



○ = Corner monument restored.

History of original corner establishment:

Corner set in the 1930 resurvey.

Description of corner evidence found:

Found old stake standing marked S10 S11 S 1/16

Description of monument and accessories I established to perpetuate the original location of this corner.

Set 2" pipe with brass cap and rock mound.

B.T.'s to corner

Hard maple 8" N42W 38Ft. 9 inches

Basswood 7" S53W 36Ft. 9 inches

B.T.'s faced at base of tree and scribed BT



Dated at Antigo, Wis., this 14th day of May, 19 69.

Signature Raymond J. Hallisy Title Reg. Land Surveyor Registration No. S685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19 _____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy