## U.S. PUBLIC LAND SURVEY MONUMENT RECORD (Prepared and as required by S. A-E 7.08 W Administrative Code)

(Frepared and as required by 3. A=2 7.00 m Administrative code)
The SE corner of Section 13, T. 34 N., R. 10 E., Langlade County, W
Corner was: (check all that apply)  Restored through acceptance of an obliterated evidence location.  Restored through acceptance of a found perpetuated location.  Determined to be lost and re-established through proportionate methods.  (Show bearings and distances to PLSS corners used for proportioning.)  Restored/recovered/reestablished in a location that differs from a previously established position. (Show difference in plan view below.)
Check here if additional information is shown on the reverse side of this form.
Describe record evidence, recovered physical evidence, occupational evidence, testimonial evidence and all other evidence considered in the recovery/restoration of the corner.  1859 ORIGINAL CORNER ESTABLISHED BY HIRAM C. FELLOWS
ORIGINAL BT'S: TAM 14 S40W 12 lks. TAM 12 N15E 20 lks.  TAM 11 N10W 16 lks. HEM 8 575E 9 lks.  1881 DORR MEAS. SE TO NE CORNERS, SECTION 13 86.10ch. (5682.60')
says: FOUND ORIG. BTS TAM 12 N161/2W 25 lks., TAM 12 N5W 231/4 lks., HEM 18 545W 23 lks. 1900 DORR SUBDIVIDED SEC 13.
1936 HINTZ ORIG GONE. I RON PIN FOR COR.  SET WIT. COR. 501ks EAST. NBT W. PINE 40 N83E 281ks.  MEAS. SE TO NE CORNERS, SECTION 13 86.42 (5703,72')
1975 KELLY LOCATED WIT. COR. & FOUND 3/4" DIA. ROD W) DIT AT SURFACE OF PAVEMENT. FOUND WIT. COR. 586°30'E Z6.40'. SET 1/2"WIT. COR. WEST 33.0'. SET NAIL IN P.P. #3410-24E2 N88°W Z6.43'.
Physical description of the monument set:  2000 DEAN WILLIAMS FOUND ("I.P. AND 3/4" I. ROD AT CENTER W/DIT .5 BELOW PAVEMENT.  ZND FOUND KELLY'S WIT COR TO WEST AND P.P. DIRECT OBSERVATION BLOCKING
MAY KELLY WIT COR TO WEST. FOUND HINTZ 4" WIT. COR. UPROOTED AND LAYING DOWN.
Describe the accessories used to perpetuate the location of the corner. Include a plan view drawing and indicate accessories found/set. Describe measuring point on bearing trees. Show any topographic features that would
aid in future recovery of the corner.  E 1/4 COR. SEC. 13
3/4" REBAR
2838. REBAR
PAVEMENT EDGE -9.4 -11.2
POWER POLE # 3410- Z4EZ - WEST 7'+ S'BELOW PAVEMENT.
WEST 26= OF 4"B.C.I.P. W/WHITE VINYL
KELLY 11/2" B.C.I.P. WIT. MON. 525 SB6"05'08"W 26.24' 1.0'
TA KEBAK
3/4" REBAR
The SE
SURVEYORS SEAL corner of Section 13
T. 34 N., R. 10 E. Langlade County, W. D.
DEAN WILLIAMS certify that the
corner location shown on this record was determined by me or under my direction and control and that this 2488
DEAN WILLIAMS  corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.  DEAN  WILLIAMS  2488  SUMMIT LAKE  WIS.
I. DEAN WILLIAMS  corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.  Dean William 06/09/2000  Dean William 06/09/2000  T. 34 N., R. 10 E. Langlade County, W. DEAN WILLIAMS  VILLIAMS  SUMMIT LAKE  O = Location of corner
Signature Date

## WISCONSIN ADMINISTRATIVE CODE

A-E 7.07 Monuments. The type and position of monuments to be set on any survey shall be determined by the nature of the survey, the permanency required, the nature of the terrain, the cadastral features involved, and the availability of material.

History: Cr. Register, February, 1987, No. 374, eff. 3-1-87.

## A-E 7.08 U.S. public land survey monument record.

- (1) WHEN MONUMENT RECORD REQUIRED A U.S. public land survey monument shall be prepared and filed with the county surveyor's office as part of any land survey which includes or requires the perpetuation, restoration, reestablishment or use of a U.S. public land survey corner, and,
- (a) There is no U.S. public land survey monument record for the corner on file in the office of the county surveyor or the register of deeds for the county in which the corner is located; or,
- (b) The land surveyor who performs the survey accepts a location for the U.S. public land survey corner which differs from that shown on a U.S. public land survey monument record filed in the office of the county surveyor or register of deeds for the county in which the corner is located, or,
- (c) The witness ties or U.S. public land survey monument referenced in an existing U.S. public land survey monument record have been destroyed or disturbed.
- (2) FORM REQUIRED. A U.S. public land survey monument record shall be prepared on the board-approved form or on a form substantially the same as the board-approved form which includes all the elements required by this section. A form used for this purpose shall be entitled, "U.S. Public Land Survey Monument Record".

Note: A copy of the board-approved form is available from the Department of Regulation and Licensing, Bureau of Business and Design Professions, 1400 East Washington Avenue, P.O. Box 8935, Madison, Wisconsin 53708.

- (3) MONUMENT RECORD REQUIREMENTS. A U.S. public land survey monument record shall show the location of the corner and shall include all of the following elements:
- (a) The identity of the corner, as referenced to the U.S. public land survey system;
- (b) A description of any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence considered by the surveyor, and whether the monument was found or placed;
- (c) Reference ties to at least 4 witness monuments. Witness monuments shall be concrete, natural stone, iron, bearing trees or other equally durable material, except wood other than bearing trees;
- (d) A plan view drawing depicting the relevant monuments and reference ties which is sufficient in detail to enable accurate relocation of the corner monument if the corner monument is disturbed;
- (e) A description of any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished;
- (f) Whether the corner was restored through acceptance of an obliterated evidence location or a found perpetuated location;
- (g) Whether the corner was reestablished through lost-corner-proportionate methods;
- (h) The directions and distances to other public land survey corners which were used as evidence or used for proportioning in determining the corner location; and,
- (i) The stamp and signature or seal and signature of the land surveyor under whose direction and control the corner location was determined and a statement certifying that the U.S. public land survey monument record is correct and complete to the best of his or her knowledge and belief.

History: Cr. Register, February, 1987, No. 374, eff. 3-1-87; am. (1) and (3) (c), Register, May, 1989, No. 401, eff. 6-1-89

County of LANGLADE	
Outily Ol. Killing & ROK. T	ss.
certify that on the 3RP of PECEMBER, 1925 evidence of the SECTIONS 13, 18, 24. Township 34, No 10E 11E, Fourth Principal as described hereon; and that from th I established a new monument and as described hereon to perpetuate t location of this corner.	, I found  f /9  rth, Range Meridian, is evidence accessories
Resident witnesses:	
	<del>-</del>
	1
<del> </del>	
<del></del>	
<del>-</del> <del>-</del>	

CERTIFIED	LAND	CORNER	RESTORATION

History of original corner establishment:



Index No. N-25 24-10

Description of corner evidence found:

William of FUNCH MARK AT SURFACE OF BLACK TOP ROAD.

Description of monument and accessories I established to perpetuate the original location of this corner. SET NEW WITNESS CORNER. 2" B.I.P. WITH BRASS

SET NEW WITNESS CORNER.  2" B.I.P. WITH BRASS  CAP MARKED:  COR WC  GOT 34N  RIOE  13   18  24  19  COR 37 FT EAST  3 DEC 1975  WEST-33'  WEST-33'	1	Ye LKS W	
Dated at ELCHO	Wis., this	day of <b>DECEMBER</b> , 19 <b>75</b>	•
Signature William F. Kolly (County Surveyor, Register)	Title <b>REGISTERED</b> A. I Land Surveyor, or other duly a	AND SURVEYOR Registration No. 5 109 authorized official)	<b>'8</b>
Office of Register of Deeds, County of instrument was filed in this office for record at	rd on the	day of 19	hin
(Register of Deeds)			
	n		