

CERTIFIED LAND CORNER RESTORATION

Index No. N-11

State of Wisconsin }
County of LANGLADE } ss.


I RAYMOND J. HALLISY, do hereby certify that on the 4th day of APRIL, 1981, I found evidence of the SOUTH 1/4 corner of SECTION 16 Township 34, North, Range 10E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

History of original corner establishment:

ESTABLISHED IN 1937 RESURVEY

Description of corner evidence found:

4" IRON PIPE WITH BRASS CAP
ROCK MOUND



Resident witnesses:


.....
.....
.....

Description of monument and accessories I established to perpetuate the original location of this corner.

NEW BT'S

5" HARD MAPLE S84E 2' 10"
12" BASSWOOD clump S58W 12' 8"
7" HARD MAPLE S34E 30' 8"

FORM 985 H. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

Dated at ANTIGO, Wis., this 4th day of APRIL, 1981.

Signature Raymond J. Hallisy Title REGISTERED LAND SURVEYOR Registration No. 5685
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19..... at..... o'clock..... M.

.....
(Register of Deeds)

By..... Deputy