

CERTIFIED LAND CORNER RESTORATION

Index No. R-11

State of Wisconsin }  
County of LANGLADE } ss.

I Raymond J. Hallisy, do hereby certify that on the 28th day of MARCH, 1981, I found evidence of the South 1/4 corner of SECTION 21 Township 34, North, Range 10 E, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:


.....  
.....  
.....

History of original corner establishment:

ESTABLISHED IN 1937 RESURVEY

Description of corner evidence found:

4" IRON PIPE WITH BRASS CAP  
BT. 14" HEM S60W 22.7 LKS




Description of monument and accessories I established to perpetuate the original location of this corner.

NEW BT's

8" HARD MAPLE N50W 14' 1"  
5" " " N74E 1' 4"  
4" BASSWOOD S40E 8' 3"

FORM 985 K. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

Dated at ANTIGO, Wis., this 28th day of MARCH, 1981.

Signature Raymond J. Hallisy Title Registered Land Surveyor Registration No. 5685  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of \_\_\_\_\_, I hereby certify that the within instrument was filed in this office for record on the \_\_\_\_\_ day of \_\_\_\_\_, 19\_\_\_\_ at \_\_\_\_\_ o'clock \_\_\_\_\_ M.

(Register of Deeds)

By \_\_\_\_\_ Deputy