

CERTIFIED LAND CORNER RESTORATION

34-10

Index No. AJ 2-25

State of Wisconsin }
County of LANGLADE } ss.

I ROBERT J. POSS do hereby certify that on the 5TH day of AUGUST, 19 70, I found evidence of the S¹⁶ COR. corner of SECS. 24 & 19 Township 34 N, North, Range R 10 E & R 11 E, Fourth, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.


Resident witnesses:

LEIGHTON REYNOLDS.

History of original corner establishment:

Description of corner evidence found:


FOUND SQUARED STAKE MKD 1/16 - OTHER MARKS OBLITERATED BY WEATHER
IRON PIPE ALONG SIDE.



Description of monument and accessories I established to perpetuate the original location of this corner.

SET 2" IRON PIPE - PAINTED ORANGE W/BRASS CAP MKD.
S¹⁶

SEC. 24 SEC 19
T34 N R10 E R11 E



Dated at ELCHO, Wis., this 8TH day of AUGUST, 19 70.

Signature Robert J. Poss Title REG. LAND SURVEYOR Registration No. S-0001
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19 _____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy

○ = Corner monument restored.