State of Wisconsin } ss.	Н
County of LANGLADE	
I. WILLIAM F. KEUX, do hereby certify that on the day of DECEMBER, 19.75, I found evidence of the 1/4 SECTION corner of SECTIONS 24 19 Township 34, North, Range Note North, Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.	D A
Resident witnesses:	
	D
	s)
T. 34N R. 10E.	N A
	D
	Si
	O in at
	••
O = Corner monument restored.	В

CERTIFIED LAND CORNER RESTORATION	MISCONS	Index No	-35
History of original corner establishment:	WILLIAM F. KELLY S1098 ELCHO, WIS. SURVEY SURVEY	***	
Description of corner evidence found:	William S. K	ally	
LOCATED CORNER SET ON SURVEY IN 197 TIED CORNER INTO WITNESS CORNER	3 BY W.F. KELLY	FROM WITNESS	CORNER, CORNER,
Description of monument and accessories I established to	perpetuate the original	location of this corner.	
ANDE SOUTH HUNTING RIVER RO. THE WITH	R.R. SPIKE IN R SET FROM WIT	D. FOUND IN PLACE. F. COR. & WIT. STONE.	
1/45 24 19 W.C. BOND WEST 33.0'	EAST 33.0'	GALV. I.P.	
S-17-38 IN PLACE. OR 50 LKS WIT. STONE - 21x31 STONE MITH HARK	PI	rop. corner	
Dated at ELLHO ON E. FACE., Wis., this	3 Ro day of	DECEMBER.	, 19 <i>25</i>
Signature Wellam 5. Kelly Title RE613 (County Surveyor, Registered Land Surveyor, or	TERED LAND SUR	NEYOK Registration No.	51098
Office of Register of Deeds, County ofinstrument was filed in this office for record on the		, I hereby certify that	the withir , 19
at			
(Register of Deeds)	······		
_	Danutu		