

CERTIFIED LAND CORNER RESTORATION

Index No. V-2A


State of Wisconsin }
County of Langlade } ss.

I, Daniel K. Plegger, do hereby certify that on the 3rd day of December, 1980, I ~~found~~ established ~~at the~~ E 1/16 corner of sections 25 and 36 Township 34, North, Range 10 East, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:



FORM 983 M. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

History of original corner establishment:

Found old squared cedar post lying 12.00 feet east of our new position.

Description of corner evidence found:

Ran traverse from section corner 25-36 (34-10) and 30-31 (34-11) to 1/4 corner between sections 25 and 36 for a distance of 2523.874 feet at bearing S88-58-31W. Set E 1/16 corner 1261.937 feet intermediate.

Description of monument and accessories I established to perpetuate the original location of this corner.

Set a 1-1/2" I.D. iron pipe with screw-on brass cap - stamped:
Projecting 12" above ground.

Marked NBT's:

Maple 5" N85°E 3.68 feet
W. Spruce 8" S8°W 20.55 feet
Maple 6" N17°W 12.55 feet
scribed 1/16 B.T.

T34N R10E
E 1/16 S + 25
 S + 36
S1537-1980

Dated at Rhineland, Wis., this 8th day of April, 1981.

Signature Daniel K. Plegger Title Registered Land Surveyor Registration No. 1537
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy