


CERTIFIED LAND CORNER RESTORATION

Index No. V-19

State of Wisconsin }
County of Langlade } ss.

I Daniel K. Pleoger, do hereby certify that on the 19th day of September, 1980, I found evidence of the Quarter corner of Sections 26 and 35 Township 34, North, Range 10 East, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:



History of original corner establishment:

Original corner established by J.L. Nowlin, Deputy Surveyor, in 1865, from which Tamarack 8" bears S15°W 12 links and Tamarack 10" N25°E 18 links. In 1937 Langlade County surveyors found rotted stake and newer scribed stake. Found original tamarack 10" N25°E 18 links rotted stump.

Marked NBT's:

Spruce 3" S27°E 27.3 links
Spruce 4" S26°W 43.6 links

Description of corner evidence found:

Recovered a 4" iron pipe filled with concrete and capped with a 4" brass cap - stamped Projecting 12" above ground.

OBT's:

Spruce 3" S27°E 27.3 links, now a rotted stump
Spruce 4" (6") S26°W 43.6 links, now dead - scribed B.T.


Langlade County
T34N R10E
1/4 S 26
 S 35
12-7-37

Description of monument and accessories I established to perpetuate the original location of this corner.

Monument left as recovered.

Marked N.B.T.'s:

Black Spruce 5" S34°E 14.55 feet
Black Spruce 4" S69°E 20.65 feet scribed BT
Tamarack 4" S80°W 21.34 feet



○ = Corner monument restored.

Dated at Rhineland, Wis., this 18th day of February, 1981.

Signature Daniel K. Pleoger Title Registered Land Surveyor Registration No. 1537
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy