

CERTIFIED LAND CORNER RESTORATION

Index No. U-20

State of Wisconsin }
County of Langlade } ss.

I Daniel K. Pleoger, do hereby certify that on the 29th day of October, 1980, I ~~found~~ established ~~the~~ SE 1/16 corner of Section 26 Township 34, North, Range 10 East, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.


History of original corner establishment:

No evidence of any previous corner.

Description of corner evidence found:

Corner established by subdivision of SE 1/4 - Section 26.
Location of SE 1/16 corner is S87-52-54E 1289.621 feet of SC 1/16 corner and S0-40-10E 1304.498 feet of E.C. 1/16 corner.

Resident witnesses:



Description of monument and accessories I established to perpetuate the original location of this corner.


Set a 1-1/2" I.D. iron pipe with screw-on brass cap, stamped:
Projecting 18" above ground.

Marked NBT's:

Sugar 5" N11°W 16.21 feet
Sugar 5" S4°W 2.19 feet scribed 1/16 - BT
Maple 5" N62°E 29.86 feet

T34N R10E
SE 1/16 S 1/26
S1537-1980

FORM 983 M. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

Dated at Rhineland, Wis., this 18th day of February, 1981.

Signature Daniel K. Pleoger Title Registered Land Surveyor Registration No. 1537
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy