

CERTIFIED LAND CORNER RESTORATION

Index No. U-18

State of Wisconsin }
County of Langlade } ss.

I Daniel K. Pleoger, do hereby certify that on the 30th day of October, 19 80, I ~~re-established~~ established the SW 1/16 corner of Section 26 Township 34, North, Range 10 East, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.


History of original corner establishment:

No evidence of any previous corner.

Description of corner evidence found:

Corner established by subdivision of the SW 1/4.
Location of SW 1/16 corner is S 0-05-12 W 1307.644 feet of WC 1/16.
Corner and N87-20-38W 1331.45 feet of SC 1/16 corner.

Resident witnesses:



Description of monument and accessories I established to perpetuate the original location of this corner.


Set a 1-1/2" I.D. iron pipe with screw-on brass cap - stamped:
Projecting 12" above ground.

Marked NBT's:-

Sugar 6" S23°W 33.92 feet
Sugar 8" N30°E 39.24 feet - scribed 1/16 B.T.
Hemlock 7" N68°E 22.19 feet

T34N R10E
SW 1/16 S 26
S1537-1980

FORM 985 H. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

Dated at Rhineland, Wis., this 24th day of February, 1981

Signature Daniel K. Pleoger Title Registered Land Surveyor Registration No. 1537
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19 _____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy