

CERTIFIED LAND CORNER RESTORATION

Index No. V-17

State of Wisconsin }
County of Langlade } ss.

I, Daniel K. Pleoger, do hereby certify that on the 19th day of September, 1980, I found evidence of the Section Corner corner of Sections 26, 27, 34, 35 Township 34, North, Range 10 East, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:



History of original corner establishment:

Original corner established by J.L. Nowlin, deputy surveyor, in 1865 from which White Birch 12" bears N35°W 25 links and White Pine 24" bears N61°E 18 links. Corner recovered in 1937 by Langlade County surveyors. Recovered original white pine B.T. N61°E 18 links.

Marked NBT - White Pine 12" N18°W 17.6 links

Description of corner evidence found:

Recovered a 4" iron pipe with 4" brass cap - stamped: Projecting 12" above ground.

O.B.T.'s - Original Wh. Pine stump S61°E 18 links, scribed R10E - S26 - B.T.
White Pine 12" N18°W 17.6 links, now a stump - scribed S27 - B.T.

Langlade County
T34N R10E
27 | 26
34 | 35
11-10-37


Description of monument and accessories I established to perpetuate the original location of this corner.

Monument left as recovered.

Marked NBT's:

Maple 7" N38°W 2.60 links
W. Pine 7" N56°E 9.30 links scribed S.C. - B.T.
Hemlock 6" S47°E 29.00 links

FORM 985 H. C. MILLER CO., MILWAUKEE



○ = Corner monument restored.

Dated at Rhineland, Wis., this 18th day of February, 1981

Signature Daniel K. Pleoger Title Registered Land Surveyor Registration No. 1537
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of _____, I hereby certify that the within instrument was filed in this office for record on the _____ day of _____, 19____ at _____ o'clock _____ M.

(Register of Deeds)

By _____ Deputy