O = Corner monument restored

ERTIFIED LAND CORNER RESTORATION	ERTIFIED	LAND	CORNER	RESTORATION
----------------------------------	----------	------	--------	-------------

Index No. V-16

History of original corner establishment:

No evidence of any previous corner.



Description of corner evidence found:

Ran traverse from section corner 26, 27, 34, 35, to 1/4 corner between sections 34 - 27 for a distance of 2525.943 feet at bearing S89-37-43W. Set E 1/16 1262.972 feet intermediate.

Description of monument and accessories I established to perpetuate the original location of this corner.

Set a 1-1/2" I.D. iron pipe with screw-on brass cap - stamped:

Monument projects 12" above ground.

Marked NBT 
Sugar 7" S29°E 13.10 feet

Sugar 6" S85°E 19.23 feet

Sugar 5" N3°E 14.46 feet

scribed 1/16 B.T.

T34N R  $10^{\circ}$  E  $1/16 \stackrel{S}{s} + \frac{27}{34}$  S 1537 - 1980

Dated at Rhinelander , Wis., this 16th day of October , 1980

Signature Daniel K. Pleage Title Registered Land Surveyor Registration No. 1537

(County Surveyor, Registered Land Surveyor, or other duly authorized official)

(Register of Deeds)

By.....Deputy