
State of Wisconsin

## CERTIFIED LAND CORNER RESTORATION

History of original corner establishment:

No evidence of any previous corner.



Description of corner evidence found:

Corner established by proportional measurement. Computed line from 1/4 corner between sections 27 and 34 to C 1/4 corner section 27 is N1-12-57E 2583.233 feet. Set S.C. 1/16 1291.616 feet intermediate.

Description of monument and accessories I established to perpetuate the original location of this corner.

Set a 1-1/2" x 16" iron pipe in centerline of Brady Lane 4" below surface for true corner. Set a 1-1/2" I.D. iron pipe with screw-on brass cap - stamped:

Witness corner projects 18" above ground.

Marked NBT's to true corner Maple 6" S65°E 38.20 feet
Hemlock 6" N26°W 52.46 feet

scribed 1/16 B.T.

T34N R10E SC 1/16 S - 27 W.C. W 40 ft. S1537-1980

Dated at Rhinelander	, Wis., this	16th	day of	October	, 19.80
Signature Daniel K. Pleoger (County Surveyor, Registered	Title Res	gistered , or other du	Land Surveyor	Registration	No. 1537
Office of Register of Deeds, County of instrument was filed in this office for record at				, I hereby certify t	hat the within
(Register of Deeds)					

.Deputy