History of original corner establishment:

No evidence of any previous corner.

Description of corner evidence found:

Total distance from section corner 28-29-32-33 to 1/4 corner between sections 28 and 29 is 2766.84. Set S 1/16 1383.42 intermediate.

Description of monument and accessories I established to perpetuate the original location of this corner.

Set a 3/4" x 25" iron pipe on east edge of east-west logging road. Drove iron pipe 12" below ground.

Marked NBT's:

Sugar 5" N45E 21.26'
Maple 7" N72W 36.40'
scribed 1/16-B.T.

Dated at	Rhinelander	Wis., this.	19th	day	of	December	19 83
Signature	Slew Garfler (County Surveyor, Register	Title	Registered	Land y authoria	Surveyor zed official)	Registrati	ion No. S-1682
instrument	egister of Deeds, County of was filed in this office for reco'clock	ord on the			lay of	I hereby certif	y that the within
	(Register of Deed	s)		-			

O = Corner monument restored.

State of Wisconsin

certify that on the 11th day

Township 34 North, Range 10 East Fourth Principal Meridian, as described hereon; and that from this evidence

I established a new monument and accessories

as described hereon to perpetuate the original location of this corner.

19 83 , I fannsk

CRANDON

R10E

County of Langlade

Glen Barker

Resident witnesses:

H. Wagoner

S 1/16

J, Claflin, Reg

T34N

SS.