U.S. PUBLIC LAND SURVEY MONUMENT RECORD


NOTE: This form is intended and designed to fulfill all requirements of Wisconsin Administrative Code, Chapter A-E 7 .08 U.S. Public Land Survey Monument Record (3)(a)(b)(c)(d)(e)(f) (g)(h)(i). An additional sheet may be added if necessary to conform with said regirements.

(a)Corner location: Township 34 North

Range_10_East/West

Town/City/Village ___ELCHO

County <u>LANGLADE</u>



(b)(f)(g)(h) Description of monument found at this corner and if it was accepted, state all evedence (material, testimonial, occupational, plats, records, other monuments) used as a basis for accepting. Ifnot accepted or if nothing was found, state evidence used as basis for establishing location. If reestablished through lost corner propotionate methods, indicate all monuments, distances and directions used to establish. Indicate type of monument found or set and sign post.


JULY, 1865 - JAS T. NOWLIN, DEPUTY SURVEYOR, SET CORNER POST TO SECTIONS 29, 30, 31, AND 32.

12" BIRCH N40E, 15 LINKS, 6" BIRCH N45"W, 10 LINKS.

1936 - D. A. HINTZ, E. F. KOWALKE, C. W. BORTH - RECOVERED NW SECTION CORNER SET BY NOWLIN. RECOVERED REMAINS OF 10" BIRCH B.T. MARKED STONE 2' X 2' X 30", S69'E, 12.9 LINKS.

7-26-99 - NICOLET SURVEYING - FOUND HINTZ'S 4" CAPPED IRON PIPE. MADE NEW TIES

(c)(d)(e) Plan view of corner with ties to at least 4 witness monuments. If in disagreement with previously established corner, show the distances between the two corners and also indicate the ties to the disputed corner.



(type or print name) certify that the corner location on this record was determined by me of under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Signature Van Lewis 7/26/99




1-5

State	of Wise	consin) ss		
County of	LANGLADE	l	} ss.		
I WILLIAM F. KELLY , do hereby certify that on the					
Resident wi					
JDREW		••••••			
T34N-R10E					
	l	1	1		
	 -	1			
	¦	-¦ 1	 		
	 		· 		
- -	¦2	÷	+		
	l [1	1		
	! !	! -¦	<u> </u>		
	, 1 ,	1			
	! !	1			
(!)	·				

O = Corner monument restored.

CEDTICIEN	LAND	CODNED	RESTORATION	M
しこれまけしい	LAND	CURNER	KESTUKATI	JIN

History of original corner establishment:



Description of corner evidence found:

LOCATED A 4" BRASS CAP SET ON OCTOBER 20, 1937.

CORNER IS LOCATED APPROXIMATELY 50 FEET NORTH OF W. ELCHO ROAD.

Description of monument and accessories I established	to perpetuate the original location of this corner.
N Soft MAPLE	BRASS CAP MARKED: CORNER WITNESSED WITH NEW BEARING TREES. TREES BLAZED NBT ON TRUNK AND MARKED WITH
	A + AT BASE. 59 day of APRIL , 19.75
	GISTERED LAND SURVEYOR Registration No. S. 1098
Office of Register of Deeds, County of	, I hereby certify that the within
(Register of Deeds)	